SITE INSPECTION OF NIXDORFF-LLOYD CHAIN COMPANY MARYVILLE, MISSOURI

#### Prepared for:

U.S. Environmental Protection Agency Region VII 324 E. Eleventh Street Kansas City, MO 64108

EPA Contract Number 68-01-6515 Work Assignment RO7-005 PN 3597-19

Prepared by:

PEDCo Environmental, Inc. 11499 Chester Road P.O. Box 46100 Cincinnati, OH 45246-0100

RECEIVED

SEP 0 3 1982

AIR AND HAZARDOUS MATERIALS DIVISION

R00342902

RCRA RECORDS CENTER

August, 1982

# GROUND WATER MONITORING COMPLIANCE INSPECTION REPORT NIXDORFF-LLOYD CHAIN COMPANY, MARYVILLE, MISSOURI

#### Geology

The facility is located in Nodaway County on moderately dissected plains topography. The underlying bedrock is sedimentary rock of Pensylvanian age.

Overlying the bedrock are deep loess and drift deposits of glacial origin.

Hydrogeology

The hydrogeology of the site is indicated by the logs of the borings and water level measurements completed prior to installation of the monitoring wells. Comparison of borehole water level depths noted on the boring logs indicates that Boring B-1 (also Monitoring Well 1) is apparently the upgradient well. This has not been confirmed, because reference elevations of the tops of the well casings had not yet been established (surveyed) at the time of the inspection. Mr. Hughes said that this would be done shortly. The difference in ground surface elevations among the four (4) monitoring wells appeared to be less than 5 feet. The depth to water in B-1 was reported to be 8.1 feet below ground upon completion of the boring, while the depths to water in B-2, B-3, and B-4 were reported to be 12.0 feet. Therefore, it would appear that B-1 is likely the upgradient well as was intended. On this basis, the direction of ground water flow would appear to be toward the southeast.

All 4 borings were completed to depths of 20.5 feet below ground. Boring B-1 encountered silty clay from ground surface to completion. B-2 and B-3 encountered silty clay from 2 to about 8 feet (topsoil indicated from 0 to 12

feet). From about 8 to 14 feet, B-2 and B-3 encountered sandy clay; below about 14 feet to completion depths B-2 and B-3 encountered clayey sand and/or sand. Boring B-4 encountered silty clay from 1 to 15 feet (fill indicated from 0 to 1 foot). From 15 feet to completion depth, B-4 encountered sandy clay.

Well and water level depths measured during the inspection were as follows:

<u>Well</u>	Well depth (ft below top of casing)	Water level depth (ft below top of casing)
1	22±	5.3±
2	22±	7.2±
3	19±	<b>4.9</b> ±
4	21±	5.6±

The measured water levels may not be true static levels, however, because the wells had been bailed by Mr. Hughes on 7/13/82 and the water levels may have still been recovering (rising) at the time of the inspection.

It was noted that two (2) factory supply wells are situated near the northeast and southeast corners of the plant. These wells were recommended to be pumped at the rates of 25 to 35 gallon per minute by Layne-Western Co., the firm who drilled and installed the wells in 1970. Well #1 is 30.5 feet below ground surface and Well #2 is 27.5 feet below ground surface. Both supply wells are within 300 feet of Monitoring Well #3. Based on this limited information, it would appear that pumping of the factory wells may be influencing the ground water flow direction near the surface impoundment.

## Ground Water Monitoring Program

Nixdorff-Lloyd Chain has just recently implemented a ground water monitoring program. The monitoring wells were installed on 6/28/82. Water samples had not been collected as of 7/14/82, but the wells were scheduled to be sampled July 15 or 16.

#### Attachments

- Form 1 General Information and Form 3 Hazardous Waste Permit Application
- Kansas City Testing Lab Monitoring Well Installation Report
- Layne-Western County Test Drilling and Water Supply Well Report

### APPENDIX A-1

## FACILITY INSPECTION FORM FOR COMPLIANCE WITH INTERIM STATUS STANDARDS COVERING GROUND-WATER MONITORING

Company Nar	me: Nix dorff-Lloyd Chain	; EPA LD. Numbe	r: M0d09	9238784	
Company Add	dress: 2500 E. 1st Street	; Inspector's Nam			
	Maryville, MO	_	N	-L Chain	
Company Cor	ntact/Official: Ed Hughes	_; Branch/Organiz	ation: S	t. Louis, MC	
Title: Proj	ect Engineer	; Date of Inspect	ion:7/	14/82	
Type of facil	ity: (check appropriately)	<u>Yes</u>	<u>No</u>	Unknown	Waived
a) b) c) d)	surface impoundment landfill land treatment facility disposal waste pile*	<u>x</u> (1)			
Ground-Wate	r Monitoring Program				
	ground-water monitoring program d prior to site visit?	_x			
a)	Was the ground-water program reviewed at the facility prior to site inspection?	N/A			
(capable impact of the upper contract)	cound-water monitoring program of determining the facility's on the quality of groundwater in ermost aquifer underlying the been implemented? 265.90(a)	<u>x</u>			

<sup>\*</sup>Listed separate from landfill for convenience of identification.

			Yes	No	Unknown Waived	
3.	inst hydr of t	at least one monitoring well been alled in the uppermost aquifer raulically upgradient from the limit he waste management area?	<u>x</u>			_
	a)	Are ground-water samples from the uppermost aquifer, representative of background ground-water quality and not affected by the facility (as ensured by proper well number, locations and depths?)			х	
4.	inst lim	ve at least three monitoring wells been alled hydraulically downgradient at the it of the waste handling or management a? 265.91(a)(2)	_X			
	a)	Do well number, locations and depths ensure prompt detection of any statistically significant amounts of HW or HW constituents that migrate from the waste management area to the uppermost aquifer?	<u>x</u>			
5.	are	ve the locations of the waste management as been verified to conform with infortion in the ground-water program?	<u>x</u>		<u></u>	
	a)	If the facility contains multiple waste management components, is each component adequately monitored?	N/A			
6.	of agr	the numbers, locations, and depths the ground-water monitoring wells ee with the data in the ground-water nitoring system program? No", explain discrepancies.	<u>x</u>			
7.	We	ll completion details. 265.91(c)			, *	
		<ul> <li>a) Are wells properly cased?</li> <li>b) Are wells screened (perforated)</li> <li>and packed where necessary to enable</li> </ul>	X			
•		sampling at appropriate depths?  c) Are annular spaces properly sealed to prevent contamination of ground-	<u>x</u>			
		water?	Х			

Ţ.

		•				Ye	No	Unknown
8.	Has a	a gro	ound-water n develope	r sampling a d? 265.92(a	nd <b>analysis</b> )	×		
	b) e)	Is the Doe and 1) S 2) S 3) S 4) A	s the plan techniques Sample col Sample pre Sample shi analytical (	ot at the factinclude process for: lection? servation?	eedur <b>es</b>	x x x x x x x x x x x x x x x x x x x	mp <u>lement</u> e	ed, 7 <u>/82)</u>
9.	sami	ples	being test	ed quarterly	n ground-water v for 265.92 (c)(1)	<u>(see</u> 8 (	a) <u>aboye</u>	)
	a)	Are	the groun	d-water san he following	nples g:			
		2)	the suitable water as a 265.92(b) Parameter ground-wa 265.92(b) Parameter ground-wa 265.92(b) (i) For each are at measu upgrace obtain monito (ii) Are pr the in	s establishing ter quality? (2) s used as ingular contaminator contaminator least four rements obtained during the covisions manifial backgr	dicators of ination?  parameter eplicate ained at each or each sample in first year of 92(c)(2) de to calculate ound arithmetic	? ?		
			para: obtai	neter conce	ee of the respective intrations or values e upgradient well(sear? 265.92(c)(2)	3	<u> x</u>	-
,	b)	fir	r facilities st year gro quirements	ound-water s	e completed sampling and analy	sis N/A		
			for the grat least a Have sam	round-water innually? 26 iples been o for the indi	btained and cators of	ed s N/A		-
				ater contami-annually?	265.92(d)(2)	N/A		-

			<u>-</u>	Yes	No	Unknown
		dete	e ground-water surface elevations ermined at each monitoring well each			
	d)	Wer	e a sample was taken? 265.92(e) e the ground-water surface elevations uated annually to determine whether the	N/A		
-		mon 265 If it	itoring wells are properly placed? .93(f) was determined that modifion of the number, location or depth	N/A		
		of n	nonitoring wells was necessary, was system brought into compliance with .91(a)? 265.93(f)	N/A		
10.	ass	s an sessn 5.93	outline of a ground-water quality nent program been prepared? (a)*	N/A	x	
	a)		es it describe a program capable determining:			
		1)	Whether hazardous waste or hazardous waste constituents have entered the ground water?	N/A		
		2)	The rate and extent of migration of hazardous waste or hazardous waste constituents in ground water?	N/A		
		3)	Concentrations of hazardous waste or hazardous waste constituents in ground water?	N/A		
	b)	hav	ter the first year of monitoring, we at least four replicate measure- ents of each indicator parameter been			
		ob'	tained for samples taken for each 11? 265.93(b)	N/A		
		1)	Were the results compared with the initial background means from the upgradient well(s) determined during the first year?	N/A		
			(i) Was each well considered individually?	N/A		
			(ii) Was the Student's t-test used (at the 0.01 level of significance)?	N/A		•
		2)	Was a significant increase (or pH decrease as well) found in the:	N/A		
			(i) Upgradient wells (ii) Downgradient wells If "Yes", Compliance Checklist A-2 must also be completed.	N/A		<u>.</u>

		t to a stand of another for	Yes	No	Unknown
11.	paran	records been kept of analyses for neters in 265.92(c) and (d)? 4(a)(1)	N/A		
12.	surfac	records been kept of ground-water ce elevations taken at the time of ling for each well? 265.94(a)(1)	N/A		
13.	eleva	records been kept of required tions in 265.93(b)? 4(a)(1)	N/A		
14.	Have Regio	the following been submitted to the onal Administrator 265.94(a)(2):	N/A		
	р Б)	initial background concentrations of parameters listed in 265.92(b) within 5 days after completing each quarterly analysis required during the first year? For each well, have any parameters whose concentrations or values have exceeded	N/A_		
	i i	the maximum contaminant levels allowed in drinking water supplies been separately identified?  Annual reports including:	N/A		
		1) Concentrations or values of parameters used as indicators of ground-water contamination for each well along with required evaluations under 265.93(b)?	N/A		
		<ul> <li>2) Any significant differences from initial background values in upgradient wells separately identified?</li> <li>3) Results of the evaluation of ground-water surface elevations?</li> </ul>	<u>N/A</u>		
		9			

NOTE: Groundwater monitoring system installed late June 1982; first samples to be obtained mid-July 1982.

<sup>\*</sup>EPA will be proposing (Spring 1982) to replace this reporting requirement with an exception reporting system where reports will be submitted only where maximum contaminant levels or significant changes in the contamination indicators or other parameters are observed. EPA has delayed compliance stage for 14 a) above until August 1, 1982 (Federal Register, February 23, 1982, p.7841-7842) to be coupled with exception reporting in the interim.

#### APPENDIX B

## GROUND-WATER MONITORING AND ALTERNATE SYSTEM TECHNICAL INFORMATION FORM

1.0	Backgr	ound Data:	
Com	pany Na	me: Nixdorff-Lloyd Chain ; EPA LD.#: MC	D099238784
Com	pany Ad	dress: 2500 E. 1st Street	
		Maryville, MO	
Inspe	ector's N	ame: G. Wittman ; Date:	7/14/82
1.1	Type o	f facility (check appropriately):	
	1.1.1	surface impoundmentx (1)	
	1.1.2 1.1.3	landfill	
	1.1.4	land treatment facility disposal waste pile	
1.2	Hasad	ground-water monitoring system been	
	establi		(Y/N) Y
	1.2.1	Is a ground-water quality assessment	
		program outlined or proposed?	(Y/N) N
		If Yes,	
	1.2.2	Was it reviewed prior to the site visit?	(Y/N) N/A
1.3		ground-water quality assessment program been	(37 /37)
	Implen	nented or proposed at the site?	(Y/N) <u>N</u>
		Appendix C, Ground-Water Quality Assessment m Technical Information Form must be utilized also	0.
2.0	Region	al/Facility Map(s)	
2.1		gional map of the area, with the facility	(Y/N) Y
	If yes,		
	2.1.1	What is the origin and scale of the map? Map sub	nitted in Part A
	•	application, appears to be U.S.G.S. map copy	
	2.1.2	Is the surficial geology adequately illustrated?	(Y/N) N

	2.1.3	Are there any significant topographic or surficial features evident?	(Y/N) <u>N</u>
		If yes, describe	
¥	2.1.4	Are there any streams, rivers, lakes, or wet lands near the facility?	(Y/N) <u></u>
		If yes, indicate approximate distances from the facility The Marvville Waterworks and associa water (Hundred and Two) is approximately 4,000	ted surface feet east of
		the facility.	
	2.1.5	Are there any discharging or recharging wells near the facility?	(Y/N) none indicated
		If yes, indicate approximate distances from the facility.	
2.2	Is a re (This i	gional hydrogeologic map of the area included? Information may be shown on 2.1)	(Y/N) N
	If yes:		
	2.2.1	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(Y/N) N/A
		If yes, describe	
	2.2.2	Is the regional ground-water flow direction	(37 (37) N/A
		indicated?	(Y/N) <u>N/A</u>
	2.2.3	Are the potentiometric contours logical?  If not, explain.	(Y/N) N/A
		·	
2.3	Is a f	acility plot plan included?	(Y/N) <u>Y</u>
	2.3.1	Are facility components (landfill areas, impoundments, etc.) shown?	(Y/N) Y
	2.3.2	Are any seeps, springs, streams, ponds, or wetlands indicated?	(Y/N) N

Ţ

d

•

	2.3.3	Are the locations of any monitoring wells, soil borings, or test pits shown?	(Y/N) <u>Y</u>
	2.3.4	Is the facility a multi-component facility?	(Y/N) N
		If yes:	
-		2.3.4.1 Are individual components adequately monitored?	(Y/N) N/A
		2.3.4.2 Is a Waste Management Area delineated?	(Y/N) N/A
.4	Is a sit	e water table (potentiometric) contour map	(Y/N) <u>N</u>
	If yes,		
	2.4.1	Do the potentiometric contours appear logical based on topography and presented data? (Consult water level data)	<b>(Y/N)</b> <u>N/A</u>
	2.4.2	Are groundwater flowlines indicated?	(Y/N) <u>N/A</u>
	2.4.3	Are static water levels shown?	(Y/N) N/A
	2.2.4	May hydraulic gradients be estimated?	(Y/N) N/A
	2.4.5	Is at least one monitoring well located hydraulically upgradient of the waste management area(s)?	<b>(Y/N)</b> N/A
	2.4.6	Are at least three monitoring wells located hydraulically downgradient of the waste management area(s)?	<b>(Y/N)</b> N/A
	2.4.7	By their location, do the upgradient wells appear capable of providing representative ambient groundwater quality data?	<b>(Y/N)</b> <u>N/A</u>
		If no, explain.	

d

**1** 

3.0	Soil Bor	ing/Test Pit Details
3.1	Were so	il borings/test pits made under the supervision dified professional? (Y/N)
	If yes,	
	3.1.1	Indicate the individual(s) and affiliation(s): John V. Zey, P.E.
-		Kansas City Testing Laboratory, Kansas City, MO 64114
	3.1.2	Indicate the drilling/excavating contractor, if known
3.2	If soil b	orings/test pits were made, indicate the method(s) ing/excavating:
	•	Auger (hollow or solid stem)X
	•	Mud rotary  Air rotary
	•	Reverse rotary
	•	Jetting
	•	Other, including excavation (explain)
3.3	List the	e number of soil borings/test pits made at the site
	3.3.1	Pre-existing 3*
	3.3.2	For RCRA compliance 4
3.4	Indicat diamet	e borehole diameters and depths (if different ers and depths use TABLE B-1).
	3.4.1	Diameter: 8 inch
	3.4.2	Depth: 20.5 feet
3.5	Were li	ithologic samples collected during drilling? $(Y/N)_{\underline{Y}}$
	If yes,	
	3.5.1	How were samples obtained? (Check method(s))
		• Split spoon X
-		Shelby tube, or similar
	-	<ul> <li>Rock coring</li> <li>Ditch sampling</li> </ul>
		Other (explain)

<sup>3</sup> test borings for installation of 2 water supply wells were completed in 1970 but are not used to monitor groundwater.

BORING NO.
DEPTH
DIAMETER

3.5.2	At what interval were samples collect	ed: Hot man	
3.5.3	Were the deposits or rock units penetr described? (boring logs, etc.)		(Y/N) <u></u>
If test	pits were excavated at the site, describures	N/A	
	Completion Detail		
	the wells installed under the supervision sional?	of a qualifie	(Y/N) <u>ү</u>
If yes			
	Indicate the individual and affiliation	, if known J	ohn J. Zey, P.E
4.1.1	Kansas City Testing Laboratory		
4.1.2	Kansas City Testing Laboratory		
4.1.2	Indicate the well construction contra		
4.1.2 List t	Indicate the well construction contra Kansas City Testing Laboratory  Laboratory		
4.1.2 List t	Indicate the well construction contra Kansas City Testing Laboratory  he number of wells at the site	ctor, if know	
4.1.2 List t 4.2.1 4.2.2 Well	Indicate the well construction contra Kansas City Testing Laboratory  he number of wells at the site  Pre-existing	2* 4	
4.1.2 List t 4.2.1 4.2.2 Well	Indicate the well construction contra Kansas City Testing Laboratory  he number of wells at the site  Pre-existing  For RCRA Compliance  construction information (fill out INFO	etor, if know  2*  4  RMATION	
4.1.2 List t 4.2.1 4.2.2 Well TABI	Indicate the well construction contra Kansas City Testing Laboratory  he number of wells at the site  Pre-existing  For RCRA Compliance  construction information (fill out INFO LE B-2)  If PVC well screen or casing is used,	etor, if know  2*  4  RMATION  are joints	

<sup>2</sup> water supply wells were installed in 1970 but are not used to monitor groundwater.

T

T

Į.

J

ſ

4

	WELL NO.	в1	B2 •	В3	В4	
	GROUND ELEVATION		NOT SU	RVEYED .		
-	TOTAL DEPTH	20	20	20	20	
	TYPE MATERIAL	PVC	PVC	PVC	PVC	
	DIAMETER	4	4	4	4	
CABING	LENGTH	13	13	13	13	
MELL C	STICK-UP	3	2	2	2	
*	TOP ELEVATION		NOT SU	RVEYED		
	BOTTOM ELEVATION					
	DEPTH TOP/BOTTOM	10 20	10 20	10 20	10 20	
	TYPE MATERIAL	PVC	PVC	PVC	PVC	
SCREEN	DIAMETER	4	4	4	4	
	LENGTH	10	10	10	10	
WELL	SLOT SIZE		NOT IN	DICATED		
	TOP ELEVATION					
	BOTTOM ELEVATION					
×	DEPTH TOP/BOTTOM	? 20	? 20	? 20	? 20	
E OR	DIAMETER	8	8	8	8	
OPEN HOLE	LENGTH	10+	10+	10+	10+	
OPEN AND/G	TOP ELEVATION					
3	BOTTOM ELEVATION					

4.3.3	Are annular spaces sealed?	(Y/N)
	If yes, describe:	
	<ul> <li>bentonite slurry</li> <li>Cement grout</li> <li>Other (explain)</li> </ul> x bentonite	e pellets
	Thicknesses of seals	
4.3.4	If "open hole" wells, are the cased portions sealed in place? $(Y/N) \frac{N/A}{}$	
	If yes, describe how:	
4.3.5	Are there cement surface seals?	(Y/N) _ <sup>Y</sup>
.4.0.0	If yes,	
	How thick?not indicated	
4.3.6	Are the wells capped?	(Y/N) _ Y
	If yes,	
	• Do they lock?	(Y/N)
4.3.7	Are protective standpipes cemented in place?	(Y/N)
4.3.8	Were wells developed?	(Y/N) <u></u>
	If yes, check appropriate method(s):	
	<ul> <li>Air lift pumping</li> <li>Pumping and surging</li> <li>Jetting</li> <li>Bailing</li> <li>Other (explain)</li> </ul>	
<b>A</b> quif	er Characterization	
l Has t	he extent of the uppermost saturated zone fer) in the facility area been defined?	(Y/N)
If yes	· 5,	v
5.1.1	Are soil boring/test pit logs included?	(Y/N)
5.1.2	Are geologic cross-sections included?	(Y/N)

J

5.2	Is there layers b	evidence of confining (low permeability) beneath the site?	(Y/N) Y
	If yes,		
-	5.2.1	Is the areal extent and continuity indicated?	(Y/N) N
	5.2.2	Is there any potential for saturated conditions (perched water) to occur above the uppermost aquifer? (Y/N) N	
		If yes, give details:	
		a) Should or is this perched zone being monitored?	(Y/N) N/A
		Explain	
	5.2.3	What is the lithology and texture of the uppermost saturated zone (aquifer)?clayey	sand and sandy clay
	5.2.4	What is the saturated thickness, if indicated?	not indicated
5.3		static water levels measured?	(Y/N) <u>Y</u>
	If yes, 5.3.1	How were the water levels measured (check me	ethod(s)).
		Electric water sounder     Wetted tape     Air line     Other (explain)	· •
	5.3.2	Do fluctuations in static water levels occur?	(Y/N) not indicated
	-	If yes,	<u>-</u>
		5.3.2.1 Are they accounted for (e.g. seasonal tidal, etc.)?	(Y/N) N/A
		If yes, describe:	

ſ

T

ſ

d

•

		5.3.2.2	Do the water level fluctuations alter the general ground-water gradients and flow directions?	(Y/N) N/A
			If yes,	
		5.3.2.3	Will the effectiveness of the wells to detect contaminants be reduced?	(Y/N) N/A
			Explain	
		5.3.2.4	Based on water level data, do any head differentials occur that may indicate a vertiflow component in the saturated zone?  If yes, explain	(Y/N)
5.4	Have a	aquifer hy	draulic properties been determined?	(Y/N) N
	If yes,			
	5.4.1	Indicate	e method(s):	
		• Fall	ing/constant head tests oratory tests (explain)  N/A	
	5.4.2	<ul><li>Trai</li><li>Stor</li><li>Lea</li></ul>	meability	N/A
	5.4.3	In case	s where several tests were undertaken, were cancies in the results evident?	(Y/N) N/A
	-	If yes,	explain	
	5.4.4	Were h	norizontal ground-water flow velocities nined?	(Y/N) N/A
		If yes,	indicate rate of movement	
			•	

Ţ

Ţ

Ţ

I

Well P	erformance	
Are th	e monitoring wells screened in the uppermost aquifer?	(Y/N) <u></u>
6.1.1	Is the full saturated thickness screened?	(Y/N) N
6.1.2	For single completions, are the intake areas in the: (check appropriate levels)	
	<ul> <li>Upper portion of the aquifer</li> <li>Middle of the aquifer</li> <li>Lower portion of the aquifer</li> </ul>	<u>×</u>
6.1.3	For well clusters, are the intake areas open to different portions of the aquifer?	(Y/N) N/A
6.1.4	Do the intake levels of the monitoring wells appear to be justified due to possible contaminant density and groundwater flow velocity?	(Y/N) <u></u>
Groun	d-Water Quality Sampling	
Is a sa includ	ampling (groundwater quality) program and schedule led?	(Y/N) <u>Y</u>
Are s	ample collection field procedures clearly outlined?	(Y/N) N
7.2.1	How are samples obtained: (check method(s))	
	<ul> <li>Air lift pump</li> <li>Submersible pump</li> <li>Positive displacement pump</li> <li>Centrifugal pump</li> <li>Peristaltic or other suction-lift pump</li> <li>Bailer</li> <li>Other (describe)</li> </ul>	
7.2.2	Are all wells sampled with the same equipment and procedures?	(Y/N) <u></u>
	If no, explain	
7.2.3	Are adequate provisions included to clean equipment	after
, , 2, 0	sampling to prevent cross-contamination between	(Y/N) N

4

To see the

€ :: :::

	7.2.4	Are orga	anic constituents to be sampled?	(1/1/
		If yes,		
Œ		7.2.4.1	Are samples collected with equipment to minimize absorption and volatilization?	(Y/N) <u>N</u>
			If yes,	
•			Describe equipment	
8.0	Sample	e Preserv	ation and Handling first samples to be coll	ected mid-July 1982
8.1	proced	appropria lures been appropri	te sample preservation and preparation n followed (filtration and preservation ate)?	(Y/N) N/A
8.2	Are sa	mples re	frigerated?	(Y/N) N/A
8.3	Are E	PA reconed to?	nmended sample holding period requirements	(Y/N) N/A
8.4	Are su	iitable co	ontainer types used?	(Y/N) N/A
8.5	Are p	rovisions conditions	made to store and ship samples under (ice packs, etc.)?	(Y/N) Y
8.6	Is a c	hain of cu	stody control procedure clearly defined?	(Y/N)
8.7			nain of custody form illustrated?	(Y/N) N
	If yes	,		
	8.7.1	sample	nis form provide an accurate record of e possession from the moment the sample en until the time it is analyzed?	(Y/N) N/A
9.0	Samp	le Analys	sis and Record Keeping	
9.1	. Is san	nple anal	ysis performed by a qualified laboratory?	(Y/N) <u></u>
	Indic	ate lab	Kansas City Testing Lab	
9.2	Are	analytica	l methods described in the records?	(Y/N) Y
	9.2.1	Are a	nalytical methods acceptable to EPA?	(Y/N) <u></u>
9.3	Are teste	the requi	red drinking water suitability parametters	(Y/N) <u>Y*</u>
9.	4 Are	the requi	red groundwater quality parameters tested for?	(Y/N) <u> </u>
	* e	xcept fl	uoride, nitrate, and pesticides	· ·

J

9.5	5 Are the required groundwater contamination indicator parameters tested for?						
9.6	Are a	(Y/N)	N				
	Ident	ify:					
	• St	emperature  becific conductance ther (describe)					
9.7	is a g	plan included to record information about each sample cted during the groundwater monitoring program?	(Y/N) _	N			
	9.7.1	Are field activity logs included?	(Y/N) _	N/A			
	9.7.2	Are laboratory results included?	(Y/N) _	N/A			
	9.7.3	Are field procedures recorded?	(Y/N)_	N/A			
	9.7.4	Are field parameter determinations included?	(Y/N)_	N/A			
	9.7.	Are the names and affiliation of the field personnel included?	(Y/N)_	N/A			
9.8	Are qual	statistical analyses planned or shown for all water ity results where necessary?	(Y/N)_	N			
	9.8.	Is an analysis program set-up which adheres to EPA guidelines?	(Y/N)_	N			
	9.8.	Is Student's t-test utilized?  If other evaluation procedure used, identify	(Y/N) _	N			
	9.8.	3 Are provisions made for submitting analysis reports to the Regional Administrator?	(Y/N)	N			
10.0	Site	Verification					
10.1	con	Plan indicating the locations of various facility ponents, ground-water monitoring wells, and surface ers?	(Y/N _	Υ			
	10.	1.1 Is the plot plan used for the inspection the same as in- the monitoring program plan documentation?	(Y/N)	Υ			
		If not, explain					

],

1

4

Į.

10.1.2	Are all of during the documenta	(1/11/	
	If not, exp	lain	
10.1.3	adjacent to	any streams, lakes or wetlands on or othe site?	(Y/N) N
	If yes, indi	cate distances from waste management a	reas
10.1.4	evident in	any signs of water quality degradation the surface water bodies?	(Y/N) N/A
	If yes, exp	olain	
10.1.5	vegetatio	ny indication of distressed or dead n on or adjacent to the site?	(Y/N) N
	If yes, ex	plain	
10.1.6	features	e any significant topographic or surficial on or near the site (e.g., recharge rge areas)?	(Y/N) N
	If yes, ex	plain	
10.1.7		nonitor well locations and numbers in not with the monitoring program tation?	(Y/N) <u>Y</u>
	If no, exp	plain	
	10.1.7.1	Were locations and elevations of the morwells surveyed into some known datum?	(Y/N) N
		If not, explain wells were to be surve	yed within one o
		two weeks	

d.

1

er entre tre

	Were the wells sounded to determine total depth below the surface?	(Y/N) <u></u>	
	If not, explain		
10.1.7.3	Were discrepancies in total depth greater than two feet apparent in any well?  If yes, explain	(Y/N) _	
wells?	und water encountered in all monitoring	(Y/N) _	
2			
	ter level elevations measured during the site	(Y/N)_	N*
visit?	ter level elevations measured during the site		
visit?  If yes, in  If not, e	ndicate well number and water level elevation_		
visit?  If yes, in  If not, e	mdicate well number and water level elevation	elevat	
visit?  If yes, in  If not, e	mdicate well number and water level elevation	elevat	
Visit?  If yes, in  If not, eshad not	mdicate well number and water level elevation	elevat	
If yes, in  If not, ethad not  Well No.	mdicate well number and water level elevation_  xplain * water level depths were measured; been surveyed  Water level depth below top casing (for	elevat	
If yes, in  If not, e. had not  Well No.	* water level depths were measured; been surveyed  Water level depth below top casing (f	elevat	

J

ď

(1) (1)

9

1


L

Ŀ

FORM					ATION	I. EPA I.D. NUMBER	Maria Ma	14	
EFA	Cons	solida	ated	Permits P	rogram	FMODØ			- 1/4
or it is a second of the secon	(Read the "General Instructions" before starting.)							NS	13 14 1
I. EPA I.D. NUMBER						If a preprinted label has b	een pr	ovide	
ZZZZZZ Momoess	جورجي					it in the designated space.  ation carefully; if any of it			
JII. FACILITY HAME						through it and enter the	correct	data	a in the
1		===	=			appropriate fill—in area bel the preprinted data is abse	nt (the	are.	a to the
	ST ST					left of the label space list that should appear), please	ts the	info	<i>imnation</i>
MARTEN	E) MÜ	to a	1-1-5	(d.5)		proper fill-in area(s) belo	w. If	the	label i
						complete and correct, you Items I, III, V, and VI (			
VI FACILITY 2500 E 1	157 97					must be completed regard items if no label has been			
LOCATION   MARYWILL	E., 140	Ë	44	60		the instructions for deta- tions and for the legal as	iled i	tem	descrip
						which this data is collected.	11110112	21101	is unde
II. POLLUTANT CHARACTERISTICS	And the state of the	1	-	1		Andrew Marie Land	غائمه دريق	THE THE	7
INSTRUCTIONS: Complete A through J to d								65" t	O SAV
questions, you must submit this form and the	supplemental	l for	m li	sted in the	parenthesis following the que	stion. Mark "X" in the box in	the th	rd co	olumn
if the supplemental form is attached. If you are is excluded from permit requirements; see Secti									tivity
is excluded from perior requirements, see Secti	on cor the n			R. X.	o, section of the instructions	z tot definitions of pold—taced	.,		W 1V1
SPECIFIC QUESTIONS	,	1	NO	FORM	SPECIFIC C	DUESTIONS	YES	HO	FORM
A. Is this facility a publicly owned treatme						(either existing or proposed)			
which results in a discharge to waters of (FORM 2A)	the U.S.?		Χ		aquatic animal production	animal feeding operation or on facility which results in a		У	
C. Is this a facility which currently results in		16	17	1.0	discharge to waters of the		19	2.0	21
to waters of the U.S. other than those de			Х			y (other than those described will result in a discharge to		Х	
A or B above? (FORM 2C)		22	23		waters of the U.S.? (FOR	M 2D) It at this facility industrial or	2.5	26	27
E. Does or will this facility treat, store, or hazardous wester? (FORM 3)	dispose of	.			municipal effluent below	the lowermost stratum con-			
Hazardous wastes: (r Orivi 5)	_	X		X		arter mile of the well bore, Irinking water? (FORM 4)		X	
G. Do you or will you inject at this facility any	produced	26	29	30		t at this facility fluids for spe-	31	3.2	33
water or other fluids which are brought to to in connection with conventional oil or natur					cial processes such as m	ining of sulfur by the Frasch		¥	
duction, inject fluids used for enhanced re oil or natural gas, or inject fluids for storage			Х			of minerals, in situ combus- covery of geothermal energy?		Х	
hydrocarbons? (FORM 4)	· -	34	38	16	(FORM 4)		1 '	36	39
<ol> <li>Is this facility a proposed stationary source one of the 28 industrial categories listed</li> </ol>						ed stationary source which is ustrial categories listed in the			
structions and which will potentially emit per year of any air pollutant regulated			Х		instructions and which v	vill potentially emit 250 tons ant regulated under the Clean			
Clean Air Act and may affect or be local					Air Act and may affect of	or be located in an attainment		Χ	
attainment area? (FORM 5)	TO WOOD	40	O.	47	erse? (FORM 5)		47	A A	
SKIP	and the state of the	in the same	ipo il		the sea College of the property procedure and	Garage Land and American and a	-		-18
1   N I X D O R F F - L L O	YD	H	A	IN	C0.				
IV. FACILITY CONTACT	4	Mary 1	4		Market Allegan		7	Te. KKAN	7.
A. NAME & TIT	LE flust, first	t, & t	title)	,	В	. PHONE (area code & no.)			
2 SOMMERHAUSER C	HARI	E	S	МЕ	CH DESR31	4 4 2 1 2 6 7 6			
15 16	Standard Same		Tomas .	The second	California de la companya de la comp	44 51 52 31		right Time	क्षा ता करियों,
V. FACILITY MAILING ADDRESS	TORPOB		-		in a market in the said	Losse La Lacore Landa Lada	فلتقيمين	د. دهاست	
	TTTTT	T-	1						
3			-4		A				
B. CITY OF TO	OWN				C.STATE D. ZIP CO	DE			
4	7777	1	1	17		1			
15 16	a programma in the same programma		STORY STR	Marketon Casa an	40 21 42 27 4	-51-		tr nerr	er-senterti vanan
VI. FACILITY LOCATION	- N. OHA	1	9.14				Name and the		A. M.
A. STREET, ROUTE NO. OF	OTHER SP	ECIF	TIC	DENTIFI	ER				
5									
B. COUNTY NAM	ME.				45		008	1.	
		-T-	7	· · · · · · · · · · · · · · · · · · ·		NOV 191	Jol	, P	
NODAWAY COUNTY				······································	70	1400			
C. CITY OR TO	DWN				D.STATE E. ZIP COL	DE F. COUNTY CODE (If known)			
6	1 1 1	1	1	1 7					
Transfer of the second					Alma Alma Alma Amaria	1	N I BAR IN CHAPTER	r72cmgh cm	may also 1943 to a colombia
EPA Form 3510-1 (6-80)						CONT		0 1 1	REVERS

1 1 1 1 1 2

II. SIC CODES (4-digit, in order of priority)		an ( Charles Wide		
A. FIRST			B. SECOND	
3 4 9 6 Production of Welded	Chain	1717 17	ckling of Steel	Rod
C. THIRD			D. FOURTH	
3 4 7 1 ging Planton at in		7	ecify)	
Zinc Electroplating		William Tolk Teachers	N/A	
III. OPERATOR INFORMATION	attender attende aparten mait, Antica facilitation de la Maille de l'acquetra de l'Ar	and the second		the said and the said of the s
<del>, , , , , , , , , , , , , , , , , , , </del>	A. NAME			B. Is the name listed in Item VIII-A also the
NIXDORFF METAL	PRODUCT	S, INC.		owner?
C. STATUS OF OPERATOR (Enter the app	ropriate letter into the an	swer box: if "Other" spe	city D P	HONE (area code & no.)
F = FEDERAL M = PUBLIC (other than S = STATE O = OTHER (specify)	jederal or state) P	(specify) N/A	A 3 1	4   4 2 1   2 6 7 6
E. STREET O	R P.O. BOX	1	1. 16 -	11 10 - 21 22 - 25
F. CITY OR TOW	/ NJ	33		
		G.STATE H.	ZIP CODE IX, INDIAN L	located on Indian lands?
ST. LOUIS,		M O 6	3 1 7 8  YE	
16		40 41 42 47	52	
EXISTING ENVIRONMENTAL PERMITS				
A. NPDES (Discharges to Surface Water)		ons from Proposed Source	es)	Anna Maria da Anna an Anna Anna an Anna
N/A	9 P N	/ A		
10 17 18 - 3	0 15 16 17 18	*	30	
B. UIC (Underground Injection of Fluids)	E. OT	HER (specify)		
O N/A	9	1,4,	9.9 (specify) 9.9 Mo.Water Po	ll. Board Permit
C. HCRA (Hazardous Wastes)	0 15 16 17 18 E. OT	HER (specify)	30	- VAIIL
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	777777	(specify)	
B N/A	9 N	/ A		
MAP	THE PROPERTY AND PROPERTY AND PROPERTY OF THE PARTY OF TH			
struch to this application a topographic ma	p of the area extending	g to at least one mile b	evond property bounde	ries. The man must show
te outline of the facility, the location of e reatment, storage, or disposal facilities, and	ach of its existing and d each well where it is	l proposed intake and njects fluids undergrou	discharge structures ea	ch of its hazardous masta
vater bodies in the map area. See instruction	is for precise requirem	ents.		
1. NATURE OF BUSINESS (provide a brief descri	iption)			
this plant produces bulk chair	from pickled.	& drawn wire.	The end product .	is hardware
onain, automobile and truck ti	ire chain. The	product can be	shipped as manu	factured, or
my be zinc electroplated.				
U CERTIFICATION (	and the same of th			The latest and the la
III. CERTIFICATION (see instructions)				
certify under penalty of law that I have pure	ersonally examined and	d am familiar with the	information submitted	in this application and all
attachments and that, based on my inquir application, I believe that the information is alse information, including the possibility o	s true, accurate and c	omplete I am aware t	t for obtaining the infolential that there are significant the significant that the significa	mation contained in the tpenalties for submitting
NAME & OFFICIAL TITLE (type or print)	B. SIGN	`		C DATE SIGNED
obert N. Schulte, President			16	11/18/80
				11/10/00
OMMENTS FOR OFFICIAL USE ONLY			A SECTION AND THE SECTION	
				1 1
Form 3510-1 (6-80) REVERSE	The state of the s			33
Form 3510-1 (6-80) REVERSE				



FORM		
. ໆ	CEDV	
ı U	W LIF	١

# FORM HAZA OUS WASTE PERMIT APPLICATIO Consolidated Permits Program

1	1.	FP	A I	.1).	NI	JM	BE	R	雅	4.5				
1	3	M		5	a	a	a	2	0	0	0	a	0	T/A
1	1.	141	10.	D	D	Ø	X	12	13	19	13	D	19	

. RC	RA			Ben W #	•	fT	his informati	on is req	uired	under Sec	tion 3	0000	RC	RA.)	1. In Old	plain	12/3/3/3	- امرار	7 1 1
-			·IC	IAL USE ON	VLY ,		411 S. 1840	AL ST			14		100						
		CAT		(yr., mo.,									co	MMENTS			The state of the s		
			-				*	and appears in white you will be have a second											_
11.	FIF	237	01	R REVISED	APPLI	CATI	ON		-0.1	STATE OF STATE				Contract of the Contract of th					
Piac	e ar	n ">	(" ir	the appropri	ate box	in A o	B below (m.	ark one t	OX O	nly) to ind	licate v	wheth	er th	is is the first app	lication you	are submi	tting for you	ır facili	ty or a
				tion. If this is ber in Item I a		rst app	lication and y	ou alrea	dy kn	iow your f	acility	's EPA	(I.D	Number, or if	this is a revise	d applica	tion, enter y	our fac	ility's
				PLICATION		an "X	" below and	provide i	he ap	propriate	date)								
	X		EΧ	ISTING FACI	LITY (S	See in <mark>st</mark> Comple	ructions for a	lefinitioi v.)	of "	'existing'	facility	<i>'</i> .		[	Z.NEW FA	CILITY (			
5	_	YR.		MO. TI DAY	FOR	EXIST	ING FACILI	TIES, PI							YR. MC.	DAY	PROVIDE	THE	DATE
8		7]		1026	OPEF (use t		N BEGAN O		ATE	CONSTR	UCTI	ONCC	MM	ENCED			TION BEC	ONA	RIS
В. І	RE		ED	APPLICAT	ION (p	lace ar	"X" below	and com	olete	Item I abo	ve)				75 74 75 7	6 21 18	1		
	_			CILITY HAS										!	2. FACILIT	TY HAS A	RCRA PER	TIME	
111.	PR	00	ES	SES – COD	ES AN	D DE	SIGN CAPA	CITIES			1	** ***							
(	iesc	ering	g co	des. If more le process (incl	lines are luding in	needec s design	i, enter the concept of the concept	the spac	the spro	pace provi vided on t	ded. I he for	fapro m <i>(Ite</i>	oce <b>ss</b> m //		used at the f t is not inclu	acility. T ded in the	en lines are p list of code	provide s below	d for , then
	1. <i>i</i> 2. l	AMI UNI	TO	DESIGN CAP. NT — Enter th F MEASURE Lused. Only t	e amour — For e	nt. each an	nount entered	f in colur	nn B	(1), enter <b>t</b>	he cod			he process. e list of unit mea	esure codes be	low that	describes the	e unit c	of
						PRO-	APPROPE								PHO-		OPRIATE L		
			PI	ROCESS		CESS	MEASUR DESIG	E FOR P N.CAPA					PE	ROCESS	CESS		SURE FOR I		SS
St	ora	ge:	_								Trea	tment					201341.132.112		
						GALLONS GALLONS				TAT	1K			TOI		ONS PER DAY	YOR		
	ASTE PILE 503 CUBIC CUBIC				CUBIC YAI	RDS OR			SUF	FACE	IM	POUNDMENT	T02	GALLO	ONS PER DAY	YOR			
	SURFACE IMPOUNDMENT S04 GALLONS OR LITERS INCIN						INER.	ATO	)R	7.03	TONS	PER HOUR		R:					
-		sal:	-	WELL		D79	GALLONS	OR LITI	ERS							GALLO	ONS PER HOUS PER HOU	JUR O	
L	NA	DFI	LL			D80	ACRE-FEE would cover	T (the vo	lume to a		oth	IER (I	Jee f	for physical, che logical treatment	nicil, TO4		S PER DAY	YOR	
							HECTARE-	one foot) OR processes not occurring in t RE-METER surface impoundments or n						occurring in tant adments or incin	5, C/:				
				POSAL		D81 D82	GALLONS LITERS PE	PER DA		2	the s	s. Des space [	crib. Provi	e the processes in ided; Item III-C	.)				
5	JRF	AC	E II	MPOUNDMEN	T	D83	GALLONS		ERS										
						UNIT								NIT OF					IT OF
UI	NIT	OF	ME	ASURE		MEAS		UNIT	OF M	EASURE				EASURE CODE	UNIT OF N	MEASURE			SURE ODE
										R DAY , .				v	ACRE-FEE				. A
C	اناز	CY	AR	DS			Y	METR	IC TO	HOUR	HOUR			w	ACRES				. в
G	ALI	10	SP	ER DAY			U	LITER	SPE	PER HOU R HOUR .				н					
othe	ami er o	an h	FO	400 gallons.	The faci	lity als	(shown in line o has an incir	<i>number</i> nerator th	rs X-1 nat ca	and X-2 in burn up	below to 20	): A f	acili	ty has two storager hour	ge tanks, one	tank can	hold 200 gal	lons an	d the
5]							T/A C		7	77	/_/	1	7	7.7.7	7-1-7	7-7-	7-7-		
				DUP		13	14 15	//		//		/ /	\		///	/ / ,	/ / /	/ /	//
ľ	Α.	PR	0-	B. PRO	OCESS	DESI	GN CAPAC	ITY		- The second sec	L C	A. PI	20-	B. PROC	ESS DESIG	SN CAP	ACITY	T	· · · · · · · · · · · · · · · · · · ·
B E		ES			0 0101			2. UNI		FOR FFICIAL	BE	CE	SS				2 UNI	OF	FICIA
NUNE	(fr	om bou	list		1. AMC (spec			SURI (ente		USE	NN	(from	list	1	. AMOUNT		OF ME SURE (enter		USE
-Z	16		18	19			27	code		. 1	Jz	16 -					(code)		
X-1	S	0	2	The second secon	600			G		TIT	1 5		T <sup>*</sup>				27 28	ΪT	TT
								+   -	+	+-+-	1	-	+-					+++	++
X-2	T	0	3		20			E			6								
1	C	0	4	69	3000			G			7					*****************			
	-		-4	00							ļ.,		ļ						
2											8								
3											9								
.1								1-1-1			10		-					++	
4		Ļ	18	19			27	1	-		10		1_						

PAGE 2 OF 5

**CONTINUE ON PAGE 3** 

OR DESCRIBING OTHER PROCESSES (code


II. PROCESSES (continued)


2A Form 3510-3 (6-80)

SPACE FOR ADDITIONAL PROCESS CODE

Conti NOT	nuec :: <b>P</b> /	dfre	om 201	pag by t	e 2. his page before completing	have	e mo	re	than	26 v	vast	es to li	st.				Foi	т Ар	prove	ed OMB No. 158-S80004
T E	_	<del>-</del>	_	_	ABER (enter from page 1)		/	'	8			F			IAL U	LY []AG			_	
1 -2					13 14 15	7	7	7	W	2	7"151	Marie Landers	DU			13 14 1	5 1.3	DU	24	
IV.		A. I	EP/	Ą	ON OF HAZARDOUS WASTI	C	UN	IT	nued						sieme ei	D. PRO		ES	ti a K	
LINE NO.	WA	AZ AST	EN	NO.	B. ESTIMATED ANNUAL QUANTITY OF WASTE	(	ME UR ente	F.				(e	ESS CO				-	2. Pf	OCE	SS DESCRIPTION not entered in D(1))
1	K	0	6,	2	1,300,000		P P			) 4		- 29 T T		29	27 - 29					
2	F	0	Q <sup>-</sup>	8	500		Р		S	0 4		1 1		1						`
3	F	0	0	9	13,250		Р		S	) 4	1	, , T-T-	ļ.,.	· 						
4																				
5												1 1								
6					1.				,			· ·	\		ļ , , ,					
7										· 					ļ.,					
8									1		_	, . <del></del>	ļ.,							
9											<u> </u>	1 -1	ļ_,_	т						
10											ļ	T-I-		· -					-	
11										7	_	1-1-	-	т —						
12			_	-			-			-	-	T-1	ļ-,-		, <del>, , , , , , , , , , , , , , , , , , </del>					
13				_			+			7	-	T 1								
14			-	-			+		T	7	-	τ		1	1-1-					
15							-					T -	<del> </del>	1				-		
16		-	-	-						<b>—</b>	-	TT-		T						-
17		-	-	-			-					1 -		τ	, ,					
18				-			-			T-		1 1		1	1-1-					
19		+	-	-					- T	T	-	г т								
20		-	-	+				-		7	_	I T		Γ	1-1-				···	8
21		+	1			-	+	-	r	T-			-	ı	7-1					
22		-	+	+			-		-	T		г-г-			1 1					
23	$\Box$	-	-	+		-	-	-		T	_	г	1							
24		+	-	+		-	-	-	-	1			1		· · · · · · · · · · · · · · · · · · ·					
25 26	-	+	-	-	7		+			7					- 1 - T				-	
EPA F	23 Orin			3 (6			36		27 -	29	27	- 29	27 -	29	27 - 29		-	Valent no.	-	CONTINUE ON REVERS

V. DESCRIPTION OF HAZARDOUS WAS continued	A STATE OF THE STA	
USE THIS SPACE TO LIST ADDITION ROCESS C	CODES FROM ITEM D(1) ON PA	
	•	
**		
,		
,		
-		
•		
SOALS NO factor from page 11		
EPA I.D. NO. (enter from page 1)		
MODØØØ299996		
/. FACILITY DRAWING		detaill
All existing facilities must include in the space provided on page 5 /I. PHOTOGRAPHS	a scale drawing of the facility (see instructions for more	55.007)
All existing facilities must include photographs (aerial or g	ground-level) that clearly delineate all existing st	ructures; existing storage,
treatment and disposal areas; and sites of future storage, to	reatment or disposal areas (see instructions for me	ore detail).
VII. FACILITY GEOGRAPHIC LOCATION	Name of the second second	
LATITUDE (degrees, minutes, & seconds)	LONGITUDE (degrees	s, minutes, & seconds)
4 0 2 0 4 5 0	<u>[8] [9] [4] [5]</u>	
VIII. FACILITY OWNER		
A. If the facility owner is also the facility operator as listed in skip to Section IX below.	n Section VIII on Form 1, "General Information", place	an "X" in the box to the left and
B. If the facility owner is not the facility operator as listed in	n Section VIII on Form 1, complete the following items	ii.
1. NAME OF FACILITY'S		2. PHONE NO. (area code & no.)
The second secon		3 1 4 - 8 7 2 - 8 5 0
Inland Realty Co.		55 56 - 58 59 - 61 62 -
3. STREET OR P.O. BOX	4. CITY OR TOWN	5.ST. 6. ZIP CODE
727 Craig Rd, P.O.Box 27479	G St. Louis	M D 6 3 1 4 1
IX. OWNER CERTIFICATION  I certify under penalty of law that I have personally exam.	nined and am familiar with the information submi	itted in this and all attached
discounts and that based on my inquiry of those individ	duals immediately responsible for obtaining the ir	Holliation, I Delieve that the
submitted information is true, accurate, and complete. I a including the possibility of fine and imprisonment.	am aware that there are significant penalties for so	John Cing raise information,
A NAME (print or type)  B. S.	MONATURE / / / /	C. DATE SIGNED
	III, VUMALITA L.	November 18, 1980
Millard S. Cohen, Vice President	Mm and I am	MOVEMBEL TO, 1900
X, OPERATOR CERTIFICATION		
I certify under penalty of law that I have personally exam documents, and that based on my inquiry of those indivi- submitted information is true, accurate, and complete. I including the possibility of fine and imprisonment.	duals immediately responsible for obtaining the H	ubmitting false information,
A. NAME (print or type)	SIGNATURE	C. DATE SIGNED
Robert N. Schulte, President	Solet Solla	November 18, 1980
EPA Form 3510.3 (6.80)	PAGE A OF 5	CONTINUE ON PAG







## KANSAS CITY TESTING LABORATORY

1669 JEFFERSON P. O. Box 8586 A.C. 913—648-2303 KANSAS CITY, MISSOURI 64114

July 1, 1982

Nixdorff-Lloyd Chain Company 916 Howard Street P. O. Box 14828 St. Louis, Missouri 63178

Attention: Mr. Edmund G. Hughes

Reference: Monitoring Well Installation

Maryville Missouri Facility

Dear Sir:

We have completed the installation of four groundwater monitoring wells at the approximate locations shown on the attached sketch. Also shown on the sketch is a typical as-built detail of the monitoring wells we installed. Boring logs were prepared by the geotechnical engineer for each well which describe the subsurface materials encountered. Copies of these boring logs are attached to this report. All wells were installed under the direct supervision of the geotechnical engineer.


Should you have any questions, please contact our office at your convenience.

Respectfully submitted,

KANSAS CITY TESTING LABORATORY

John J. Zey, P. E. Geotechnical Engineer

JJZ/mjt





## KAN CITY TESTING LABORATRY

## FOUNDATION TESTS FOR:

TEST BORING LOG

Nixdorff-Lloyd Chain Co.

Building Site:

Monitoring Well Installation

Location:

Maryville, MO

Date: 6-28-82

Boring No .:

B1

Location: see sketch

Scale: 1 inch = 3 feet

Log	Elevation	Depth in Feet	- Description	No. of Blows	Depth Inches
	_	0.0_	DARK BROWN SILTY CLAY (CL)		
	_	1.5-	LIGHT BROWN SILTY CLAY MOIST, STIFF (CL)		
			,		
	∇ -	8.1_	SAME MATERIAL		
	- -	12.0_	TAN SILTY CLAY VERY STIFF, SOME SAND (CL)		
			FREE WATER ENCOUNTERED AT 13.0'		
		20.5	TERMINATION OF BORING		



## KAN CITY TESTING LABOR RY

## FOUNDATION TESTS FOR:

TEST BORING LOG

Nixdorff-Lloyd Chain Co.

Building Site:

Monitoring Wall Installation

Location:

Maryville, MO

Date: 6-28-82

Boring No.:

B2

Location: see sketch

Scale: 1 inch = 3 feet

Log	Elevation	Depth in Feet	Description	No. of Blows	Depth Inches
	_	0.0_	TOPSOIL DARK GRAY CLAYEY SILT MOIST,	,	
7777		2.0-	LOOSE		
			BROWN SILTY CLAY MOIST, STIFF (CL)		
		8.0_	LIGHT BROWN SANDY CLAY MOIST, MEDIUM, STIFF (CL)		-
	v	15 0-	GRAY SANDY CLAY MOIST, STIFF (CL) FREE WATER ENCOUNTERED AT 12.5'		
		•	BROWN CLAYEY SAND WET, MEDIUM, STIFF (SC)		
<u> Lina</u>	-	20.5-	TERMINATION OF BORING WATER LEVEL AT 12.0' UPON COMPLETION OF BORING		



## KANSAS CITY TESTING LABORATORY

### FOUND...ION TESTS FOR:

Nixdorff-Lloyd Chain Co.

TEST BORING LOG

Building Site:

Monitoring Wall Installation

Location:

Maryville, MO

Date: 6-28-82

Boring No .:

B3

Location: see sketch

Scale: 1 inch = 3 feet

Log	Elevation	Depth in Feet	Description	No. of Blows	Depth Inches
		0.0_	TOPSOIL DARK GRAY CLAYEY SILT MOIST, LOOSE		
	9	2.0_	BROWN SILTY CLAY MOIST, MEDIUM STIFF TO STIFF (CL)		
	_	8.5	GRAY SILTY SANDY CLAY MOIST, STIFF (CL)		
	- ∇-	12.0-	SAME MATERIAL		
		13.0_	BROWN CLAYEY SAND WET, MEDIUM STIFF (SC) FREE WATER ENCOUNTERED AT 13.0'		
	-	18.0_	BROWN FINE TO MEDIUM SAND WET, LOOSE (SP)		
	-	20.5.	TERMINATION OF BORING WATER LEVEL AT 12.0' UPON COMPLETION OF BORING		



## KANTT CITY TESTING LABORATORY

### FOUNDATION TESTS FOR:

Nixdorff-Lloyd Chain Co.

Building Site:

Monitoring Well Installation

Location:

Maryville, MO

Date: 6-28-82

Boring No .:

**B**4

Location: see sketch


Scale: 1 inch = 3 feet

TEST BORING LOG

Log	Elevation	Depth in Feet	Description	No. of Blows	Depth Inche
		0.0_	FILL DARK BROWN SILTY CLAY WITH GRAVEL		
		1.0-	GRAY SILTY CLAY MOIST, STIFF (CL)		
	_	8.0-	LIGHT BROWN SILTY CLAY WITH TRACE OF SAND MOIST, MEDIUM, STIFF (CL)		
	∇-	12.0-	SAME MATERIAL		
	_	15.0_	DARK GRAY SANDY CLAY MOIST, VERY STIFF		
			(CL) FREE WATER ENCOUNTERED AT 15.0'		
///// ///// ///// /////	-	20.5_	TERMINATION OF BORING		


1⊕

MISSOURI HIGHWAY
DEPT. PROPERITY



8" DIA. HOLE

TYPICAL AS-BUILT DETAIL



SCALE:

DATE:

6-29-82

#### KANSAS CITY TESTING LABORATORY **Engineering Consultants** MONITORING WELL LOCATIONS DRAWING NUMBER NIXDORFF LLOYD CHAIN CO. 1' - 200' APPROVED BY: DRAWN BY JZ REVISED



# Layne-Western Company, Inc.

WATER SUPPLY SERVICES -

WATER WELLS . LAYNE PUMPS . TEST DRILLING . WATER TREATMENT EQUIPMENT 1010 West 39th Street . Kansas City, Missouri 64111 . AC 816 931-2353

April 22, 1970

Lloyd Chain Corporation Highway 136 Maryville, Missouri

Attention Mr. Norman Craig

Gentlemen:

TEST DRILLING AND WATER SUPPLY WELLS

We have completed the drilling of three (3) test borings and the installation of two (2) water supply wells at your facility on Highway 136 at the east edge of Mary-ville, Missouri.

Enclosed herewith are copies of our well information sheet giving details of construction of each well and our boring logs for the three (3) test holes drilled.

In addition, we are enclosing our invoice for the completed work.

In an attempt to find a deeper, more reliable aquifer (usually just above bedrock), the first two (2) test borings were drilled to the top of the bedrock surface. No suitable aquifer material was penetrated below a depth of approximately 30' so the third test boring was not drilled to the bedrock surface.

The most suitable aquifer was found in Test Borings No. 1 and 3, at a depth of approximately 20 to 30'. Since this was the only aquifer available, and the best material available, it was decided to install shallow wells at Test Borings No. 1 and 3. The south well, or Well No. 1, was installed at Test Boring No. 1-70. The north well, or Well No. 2, was installed at Test Boring No. 3-70. Well No. 1 was installed to a total depth from ground surface of 30'6" and Well No. 2 a total depth of 27'6" from ground level.

Norman Craig Page -2-April 22, 1970

A short pumping test was run on both of the completed wells and the results of the pumping test are as shown on the enclosed information sheets.

We would recommend that the pumping rate from Well No. 1 your south well, be limited to 35 gpm. The pump installed in this well, should be set 1' from the bottom of the well or 29'6" from ground level.

Well No. 2, your north well, should not be pumped at a rate greater than 25 gpm. The pump installed in this well, again should be set 1' from the bottom of the well, or 26'6" from ground level.

The above information was given to your plumber, Mr. Bill Jones, by telephone, so that he would know the pumping rates and depths the pumps should be set.

Of course, all our information is based upon the pumping tests we performed and is subject to seasonal variation. During periods of extremely wet weather when the aquifer is receiving good recharge, we would expect the wells could possibly be pumped at greater capacities than recommended, for short periods of time. On the other hand, during extreme drought conditions, the flow from the well may have to be restricted somewhat from the rates we recommend.

We appreciate your confidence in Layne-Western Company in allowing us to do this recent water supply work for you and sincerely hope our workmanship and materials have in every way met with your satisfaction. Should you have any questions regarding any of the information enclosed, or the invoicing of our work, please get in touch with us.

If we may be of further service, please let us know.

Thank you very much.

Very truly yours,

James J. Bridgforth, P.E



# Layne-Western Conpany

. •	are in the		C		
antract Nam	Lloyd C	Chain Co	rpora	tion	TEST HOLE
ob No. KC				Date4/6/70	No. 1-70 well # 1
	ryville			StateMissouri	J. Harper
Lity		F 5' S		S.E. corner of Buil	lding
est Hole Lo	cation	Distance ar	nd Directio	n from Permanent Landmark or Pre-	vious Test Hole
				TEST LOG	
FROM	то	FUNNEL	MUD PIT	Static	Water Level Measured Hours After Completion
, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		VISCOSITY	INCHES		FORMATION
0'0"	1'0"			Brown clay fill	
1'0"	5'0"			Dark gray clay, s	tiff
5'0"	11'0"			Gray clay, stiff	
11'0"	20'0"			Dark brown clayey	silt, soft
20'0"	22'0"			Gray sandy clay,	soft
22'0"	25'0"	water	2"	Gray med. to coar	se, some fine sand
25'0"	30'6"	11	5"	Gray med. to coan	rse, tr. fine sand, gravel
30'6"	80'0"		7	Gray sandy clay,	few boulders, stiff
80'0"	Total	depth			
		5 <b>'</b> 0 "	1	3'6"	4'0"
.4OTES:	Size of Pit			X	DECEP



## TEST HOLE REPORT Layne-Western Company

Contract Nar	ne Lloyd	Chain C	orpora	tion	TEST HOLE STATES
ob NoKO				_Date4/7/70	No. 2-70 WENTS
	ryville			_StateMissouri	Driller
est Hole Lo	7.5"	s.w. o	f s.w.	corner of building	3
est Hole Le	Jeanon	Distance a	nd Directio	on from Permanent Landmark or Pre	vious Test Hole
				TEST LOG	
FROM	то	MARSH FUNNEL VISCOSITY	MUD PIT LOSS	Static	Water Level Measured Hours After Completion
		FORMATION			
0'0"	1'0"			Clay fill	
1'0"	5'0"			Dark gray clay, s	tiff
5 <b>'</b> 0"	10'0"			Light gray clay,	stiff
10'0"	19'0"			Gray silty clay,	med.
19'0"	21'0"	water)		Gray fine to med.	sand
21'0"	25'0"	")	2"	Gray med. to fine	, some coarse sand
25'0"	26'0"	ıı		Gray med. to coar	se, tr. fine sand, gravel
26'0"	61'0"			Gray sandy clay,	med.
61'0"	86'0"			Gray sandy clay,	stiff
86'0"	90'0"			Gray limy shale,	hard
90'0"	Total	depth			
					•
		4'(	) <b>"</b>	3'0"	4'0"



# TEST HOLE REPORT

	THE STATE OF THE PARTY OF THE P	>	$\mathcal{L}_a$	yne- Western	Company
Contract Nar	Lloyd	Chain	Corpor	cation	TEST HOLE factory
Job NoK	С 633-В			_Date3/7/70	No. 3/70 well #2
CityMar				State Missouri	Driller_ J. Harper
Test Hole Lo	ocation225	0" N. Distance a	of No.	. 1-70 on from Permanent Landmark or Pr	evious Ţest Hole
				TEST LOG	
FROM	то	MARSH FUNNEL VISCOSITY	MUD PIT	Statio	Water Level Measured Hours After Completion
		SECONDS	INCHES		FORMATION
0'0"	1'0"			Top soil	
1'0"	4'0"			Dark gray clay, s	st <b>o</b> ff
4'0"	10'0"			Gray clay, stiff	1
10'0"	12'0"			Brown & gray sil	ty clay, stiff
12'0"	15'0"			Brown clayey sil	t, soft
	10101			a	c+; f f

10'0"	12'0"		Brown & gray silty clay, stiff
12'0"	15'0"		Brown clayey silt, soft
15'0"	19'0"		Gray sandy clay, stiff
19'0"	25'0" wate	r 6"	Gray med. to coarse, some fine sand
25'0"	27 <b>'</b> 6" wat	er 8"	Same tr. fine sand, tr. grave
27'0"	33'0"		Gray sandy clay, med.

		4'0"	3'0"	3'6"
NOTES:	Size of Pit		_X	X
				DEEP